



15540 Woodinville-Redmond Rd NE  
Building A, Suite 800  
Woodinville, WA 98072

FREEFLYSYSTEMS.COM

Date Released: October 6, 2015  
Date Effective: October 6, 2015  
Subject: **Motor fastener installation**  
Effectivity: **Altas shipped after Sep 28th**  
Require Action: **Discontinue flight operations**  
Time of Compliance: **Immediately**

#### BACKGROUND

This Service Bulletin (SB) was prompted by internal testing conducted by Freefly. Testing discovered that certain motor mounting screws were not installed with adequate torque and/ or threadlocker

We are issuing this SB because we determined the unsafe condition described previously is likely to exist or develop in select ALTAs.

This SB is being sent to affected ALTA operators.

#### RECOMMENDATIONS

Freefly recommends ALTA operators to immediately discontinue flight operations and contact customer service to schedule shipping the ALTA back to Freefly for repair.

---

For Service Information Contact:  
Freefly Customer Support  
Email: [support@freeflysystems.com](mailto:support@freeflysystems.com)  
Phone: +1 (425) 485-5500  
Hours of Operation: M-F 8am-6pm PST